Materials are beginning to flow inbound including OSB and building wrap. Diamond Kote representatives visited our site on day one to help kick off the installation procedure which included:

- Demolition of current siding
- Installation of OSB
- Installation of vapor barrier

Below shows a few pics in the sequence of installation:



CSN BUILDING RESTORATION PROJECT UPDATE – NOV 2022

